

Stock #307L

PROFILE NAME: LR TEST GUARANTEED SOAK DEVIATION 2.0

STEP: 1 STEP TYPE: RAMP HOURS: 0 MINUTES 0 SECONDS 10 GS ENABLE NO

SET POINT: 25 EVENT 1 (CH POWER): ON EVENT 2 (): - EVENT 3 () -

EVENT 5 (JUMPCOUNT): OFF EVENT 6 (JUMPCOUNT RESET): ON JUMP STEP: - JUMP COUNT: -

WAIT FOR PROCESS TEMP FUNC -:TEMP -:

STEP: 2 STEP TYPE: RAMP HOURS: 0 MINUTES 0 SECONDS 0 GS ENABLE NO

SET POINT: -40 EVENT 1 (CH POWER): ON EVENT 2 (): - EVENT 3 () -

EVENT 5 (JUMPCOUNT): OFF EVENT 6 (JUMPCOUNT RESET): OFF JUMP STEP: - JUMP COUNT: -

WAIT FOR PROCESS TEMP FUNC -:TEMP -:

STEP: 3 STEP TYPE: SOAK HOURS: 0 MINUTES 30 SECONDS 0 GS ENABLE YES

SET POINT: - EVENT 1 (CH POWER): ON EVENT 2 (): - EVENT 3 () -

EVENT 5 (JUMPCOUNT): OFF EVENT 6 (JUMPCOUNT RESET): OFF JUMP STEP: - JUMP COUNT: -

WAIT FOR PROCESS TEMP FUNC -:TEMP -:

STEP: 4 STEP TYPE: RAMP HOURS: 0 MINUTES 0 SECONDS - GS ENABLE NO

SET POINT: 150 EVENT 1 (CH POWER): ON EVENT 2 (): - EVENT 3 () -

EVENT 5 (JUMPCOUNT): OFF EVENT 6 (JUMPCOUNT RESET): OFF JUMP STEP: - JUMP COUNT: -

WAIT FOR PROCESS TEMP FUNC -:TEMP -:

STEP: 5 STEP TYPE: SOAK HOURS: 0 MINUTES 30 SECONDS 0 GS ENABLE YES

SET POINT: - EVENT 1 (CH POWER): ON EVENT 2 (): - EVENT 3 () -

EVENT 5 (JUMPCOUNT): OFF EVENT 6 (JUMPCOUNT RESET): OFF JUMP STEP: - JUMP COUNT: -

WAIT FOR PROCESS TEMP FUNC -:TEMP -:

PROFILE NAME: LRL TEST GUARANTEED SOAK DEVIATION 2.0

STEP: 6 STEP TYPE: RAMP HOURS: 0 MINUTES 0 SECONDS 0 GS ENABLE NO

SET POINT: -30 EVENT 1 (CH POWER): ON EVENT 2 (): - EVENT 3 () -

EVENT 5 (JUMPCOUNT): ON EVENT 6 (JUMPCOUNT RESET): OFF JUMP STEP: - JUMP COUNT: -

WAIT FOR PROCESS TEMP FUNC -:TEMP -:

STEP: 7 STEP TYPE: SOAK HOURS: 2 MINUTES 0 SECONDS 0 GS ENABLE YES

SET POINT: - EVENT 1 (CH POWER): ON EVENT 2 (): - EVENT 3 () -

EVENT 5 (JUMPCOUNT): ON EVENT 6 (JUMPCOUNT RESET): OFF JUMP STEP: - JUMP COUNT: -

WAIT FOR PROCESS TEMP FUNC -:TEMP -:

STEP: 8 STEP TYPE: RAMP HOURS: 0 MINUTES 0 SECONDS 0 GS ENABLE NO

SET POINT: 125 EVENT 1 (CH POWER): ON EVENT 2 (): - EVENT 3 () -

EVENT 5 (JUMPCOUNT): OFF EVENT 6 (JUMPCOUNT RESET): OFF JUMP STEP: - JUMP COUNT: -

WAIT FOR PROCESS TEMP FUNC -:TEMP -:

STEP: 9 STEP TYPE: SOAK HOURS: 2 MINUTES 0 SECONDS 0 GS ENABLE YES

SET POINT: - EVENT 1 (CH POWER): ON EVENT 2 (): - EVENT 3 () -

EVENT 5 (JUMPCOUNT): OFF EVENT 6 (JUMPCOUNT RESET): OFF JUMP STEP: - JUMP COUNT: -

WAIT FOR PROCESS TEMP FUNC -:TEMP -:

STEP: 10 STEP TYPE: Jump HOURS: - MINUTES - SECONDS 0 GS ENABLE -

SET POINT: - EVENT 1 (CH POWER): ON EVENT 2 (): - EVENT 3 () -

EVENT 5 (JUMPCOUNT): OFF EVENT 6 (JUMPCOUNT RESET): OFF JUMP STEP: 6 JUMP COUNT: 3

WAIT FOR PROCESS TEMP FUNC -:TEMP -:

PROFILE NAME: LR TEST GUARANTEED SOAK DEVIATION 2.0

STEP: 11 STEP TYPE: RAMP HOURS: 0 MINUTES 0 SECONDS 0 GS ENABLE NO

SET POINT: 25 EVENT 1 (CH POWER): ON EVENT 2 (): - EVENT 3 () -

EVENT 5 (JUMPCOUNT): OFF EVENT 6 (JUMPCOUNT RESET): OFF JUMP STEP: - JUMP COUNT: -

WAIT FOR PROCESS TEMP FUNC -:TEMP -:

STEP: 12 STEP TYPE: SOAK HOURS: 0 MINUTES 10 SECONDS 0 GS ENABLE YES

SET POINT: - EVENT 1 (CH POWER): ON EVENT 2 (): - EVENT 3 () -

EVENT 5 (JUMPCOUNT): OFF EVENT 6 (JUMPCOUNT RESET): OFF JUMP STEP: - JUMP COUNT: -

WAIT FOR PROCESS TEMP FUNC -:TEMP -:

STEP: 13 STEP TYPE: END HOURS: - MINUTES - SECONDS 0 GS ENABLE -

SET POINT: - EVENT 1 (CH POWER): OFF EVENT 2 (): - EVENT 3 () -

EVENT 5 (JUMPCOUNT): OFF EVENT 6 (JUMPCOUNT RESET): OFF JUMP STEP: - JUMP COUNT: -

WAIT FOR PROCESS TEMP FUNC -:TEMP -:

USER: OFF

STEP: - STEP TYPE: - HOURS: - MINUTES - SECONDS - GS ENABLE -

SET POINT: - EVENT 1 (CH POWER): - EVENT 2 (): - EVENT 3 () -

EVENT 5 (JUMPCOUNT): - EVENT 6 (JUMPCOUNT RESET): OFF JUMP STEP: - JUMP COUNT: -

WAIT FOR PROCESS TEMP FUNC -:TEMP -:

STEP: - STEP TYPE: - HOURS: - MINUTES - SECONDS 0 GS ENABLE -

SET POINT: - EVENT 1 (CH POWER): - EVENT 2 (): - EVENT 3 () -

EVENT 5 (JUMPCOUNT): - EVENT 6 (JUMPCOUNT RESET): OFF JUMP STEP: - JUMP COUNT: -

WAIT FOR PROCESS TEMP FUNC -:TEMP -: